

• Copper Droplets Necklace •

• Materials & Tools •

- 3 champagne 6mm square 2-hole CZ-Gem Dropz
- 3 champagne 4mm square 2-hole CZ-Gem Dropz
- 3 champagne 5mm round 1-hole CZ-Gem Dropz
- 4 crystal copper 20mm Swarovski crystal pendants
- 46 smoky topaz 4mm bicone Swarovski crystal beads
- 33" length of .018" diameter satin copper 19-strand beading wire Sterling silver S hook clasp
- 4 sterling silver EZ-Crimp ends
- 14 silver #3 crimp beads
- 9 silver 4mm lightweight jump rings
- 4 silver 6mm jump rings
- Chain-nose pliers
- Wire cutters
- Mighty Crimping tool

• Designed by Katie Hacker •



• Instructions •

1. Attach a 4mm jump ring to one hole on the CZ-Gem Dropz 6mm squares.
2. Use a 4mm jump ring to connect a CZ-Gem Dropz 4mm square to each 6mm square.
3. Use a 4mm jump ring to connect a CZ-Gem Dropz round to each 4mm square to complete the CZ-Gem Dropz pendants.
4. Attach a 6mm jump ring to each crystal pendant.
5. Cut two 16 1/2" lengths of copper beading wire.
6. Hold the wires together and string a CZ-Gem Dropz pendant onto the center.
7. On each side of the pendant, hold the wires together and pass them through the following: three 4mm crystals, crystal pendant, three 4mm crystals, CZ-Gem Dropz pendant, three 4mm crystals, crystal pendant, three 4mm crystals, crimp bead.
8. On each side of the pendant, separate the wires and pass each one through a 4mm crystal. Hold them together again and pass them through a crimp bead, a 4mm crystal and a crimp bead.
9. Repeat Step 8 two more times, then pass each wire through a 4mm crystal.
10. Hold the wires together and pass them through a crimp bead. Crimp it.
11. Use a mighty crimping tool to attach an EZ-Crimp end on each wire.
12. Use an S hook clasp to fasten the necklace ends together.

Beadalon®

• Copper Droplets Necklace •

